

Section 13.4



Exercise: Snap Lock



13.4-1 About the Snap Lock

The snap lock consists of two parts: the insert [1] and the prongs [2]; it is fastened when pushed into position [3]. The snap lock has a thickness of 5 mm and is made of a plastic material with a Young's modulus of 2.8 GPa and a Poisson's ratio of 0.35. The coefficient of friction between the materials is 0.2. The purpose of the simulation is to find out the force required to push the insert into the position and the force required to pull it out.

We will model the problem as a plane stress problem. Due to the symmetry, only one half of the model is used in the simulation.



Unit: mm.

All fillets has radius of 2 mm.

13.4-2 Start Up

Launch <Workbench>. Create a <Static Structural> analysis system. Save the project as "Snap."

[1] Double-click <Engineering Data> to input material properties.

[2] Add the material "Plastic."

[3] Include <Isotropic Elasticity> and input properties as shown.

[4] Double-click <Geometry> to create the geometry. Use <Millimeter>.

	A	B	C
1	Static Structural (ANSYS)		
2	Engineering Data	A2	Conten
3	Geometry		
4	Model		
5	Setup		
6	Solution		
7	Results		

	A
1	Contents of Engineering Data
2	Material
3	Structural Steel
4	Plastic
	Click here to add a new material

	Property	Value	Unit
1	Isotropic Elasticity		
2	Young's Modulus	2.8E+09	Pa
3	Poisson's Ratio	0.35	

13.4-3 Create Geometry in DesignModeler

[1] On XYPlane, create a sketch like this.

[2] Click <New Sketch> to create a new sketch (Sketch2) on the same plane.

Dimensions (mm):

- Top width: 20.000
- Top right offset: 10.000
- Top left offset: 5.000
- Right side offset: 7.000
- Left side offset: 12.000
- Bottom right offset: 5.000
- Bottom width: 20.000
- Bottom left offset: 7.000
- Internal vertical offset: 10.000
- Internal horizontal offset: 17.000
- Internal vertical offset: 37.000

Modify

Fillet

Chamfer

Corner

Trim

Extend

Split

Drag

Cut

Copy

Paste

Move

Replicate

Duplicate

Offset

Spline Edit

Single Select

Box Select

[4] When selecting, use <Box Select> to enclose all the entities, including points and edges. After selecting all entities, right-click-select <Duplicate Selection>.

[3] Duplicate all the entities in <Sketch1> to <Sketch2>. See next step.

A: Static Structural (ANSYS)

XYPlane

Sketch1



Sketch2

ZXPlane

YZPlane

0 Parts, 0 Bodies

[5] Hide <Sketch2>.



Concept Tools View Help

Lines From Points

Lines From Sketches

Lines From Edges

3D Curve

Split Edges

Surfaces From Edges

Surfaces From Sketches

Cross Section


[8] Select <Concept/ Surfaces From Sketches>.

Details View


Details of SurfaceSk1

Surface From Sketches	SurfaceSk1
Base Objects	1 Sketch
Operation	Add Material
Orient With Plane Normal?	Yes
Thickness (>=0)	5 mm


[9] Select <Sketch1>.




[10] After <Generate>, the prong is complete.




[11] Show <Sketch2> and hide <Sketch1>.




[12] In <Sketch2>, trim away unwanted segments.








[13] Add two fillets of radius of 2.0 mm.



[14] Select <Concept/ Surfaces From Sketches>.



[15] Select <Sketch2>.




Properties of Schematic A3: Geometry		
	A	B
1	Property	Value
2	General	
4	Geometry Source	
7	Basic Geometry Options	
16	Advanced Geometry Options	
17	Analysis Type	2D <input type="radio"/>
18	Use Associativity	<input checked="" type="checkbox"/>
19	Import Coordinate Systems	<input type="checkbox"/>
20	Import Work Points	<input type="checkbox"/>
21	Reader Mode Saves Updated File	<input type="checkbox"/>
22	Import Using Instances	<input checked="" type="checkbox"/>
23	Smart CAD Update	<input type="checkbox"/>
24	Enclosure and Symmetry Processing	<input checked="" type="checkbox"/>
25	Mixed Import Resolution	None ▼

[25] Before attaching the geometry to <Mechanical>, remember to select <2D> option (3.1-4[7]).

13.4-4 Set Up Model

Details of "Geometry"	
Definition	
Source	C:\Documents and Settings\PC\Lo...
Type	DesignModeler
Length Unit	Millimeters
Element Control	Program Controlled
2D Behavior	Plane Stress
Display Style	Part Color
Bounding Box	
Properties	
Statistics	
Preferences	

[1] Highlight <Geometry>, make sure <Plane Stress> is selected.



Details of "Multiple Selection"	
Graphics Properties	
Definition	
<input type="checkbox"/> Suppressed	No
Stiffness Behavior	Flexible
Coordinate System	Default Coordinate System
Reference Temperature	By Environment
<input type="checkbox"/> Thickness	5 mm
Thickness Mode	Refresh on Update
Material	
Assignment	Plastic
Nonlinear Effects	Yes
Thermal Strain Effects	Yes
Bounding Box	
Properties	
Statistics	

[2] Highlight <Prong> and <Insert>, assign <Plastic> to two bodies.

Details of "Frictionless - Prong To Insert"

Scope	
Scoping Method	Geometry Selection
Contact	4 Edges
Target	4 Edges
Contact Bodies	Prong
Target Bodies	Insert
Definition	
Type	Frictionless
Scope Mode	Manual
Behavior	Symmetric
Suppressed	No
Advanced	
Formulation	Pure Penalty
Interface Treatment	Add Offset, No Ramping
<input type="checkbox"/> Offset	0. mm
Normal Stiffness	Program Controlled
Update Stiffness	Never
Pinball Region	Program Controlled
Time Step Controls	None

[3] Highlight <Contact Region> and reselect the 4 edges (steps [4, 5]) as <Contact>.

[6] Reselect the 4 edges (steps [7, 8]) as <Target>.

[9] Select <Frictionless>. (We neglect friction for the first try.) Leave other settings as their default values for now.

[7] Start of target edges.

[8] End of target edges.

[4] Start of contact edges.

[5] End of contact edges.

Mesh Control - Options

Method	
<input checked="" type="radio"/> Sizing	
<input type="radio"/> Contact Sizing	
<input type="radio"/> Refinement	
<input type="radio"/> Mapped Face Meshing	
<input type="radio"/> Match Control	
<input type="radio"/> Pinch	
<input type="radio"/> Inflation	
<input type="radio"/> Gap Tool	

[10] With <Mesh> highlighted, select <Mesh Control/ Sizing>.

Details of "Edge Sizing" - Sizing

Scope	
Scoping Method	Geometry Selection
Geometry	8 Edges
Definition	
Suppressed	No
Type	Element Size
Element Size	0.2 mm
Behavior	Soft
Bias Type	No Bias

[11] Select all edges (steps [4, 5, 7, 8]) of the contact region.

Details of "Mesh"

Defaults	
Physics Preference	Mechanical
Relevance	0
Sizing	
Use Advanced Size Function	Off
Relevance Center	Coarse
Element Size	Default
Initial Size Seed	Active Assembly
Smoothing	Medium
Transition	Fast
Span Angle Center	Coarse
Minimum Edge Length	2.55870 mm
Inflation	
Advanced	
Pinch	
Statistics	
Nodes	3824
Elements	1146
Mesh Metric	Skewness
Min	4.9164385092213E-08
Max	0.84402493339901
Average	0.277008029675691
Standard Deviation	0.136776475872575

13.4-5 Set Up Analysis Settings

Details of "Analysis Settings"

Step Controls	
Number Of Steps	2
Current Step Number	1
Step End Time	1. s
Auto Time Stepping	Program Controlled
Solver Controls	
Solver Type	Program Controlled
Weak Springs	Program Controlled
Large Deflection	On
Inertia Relief	Off
Nonlinear Controls	
Output Controls	
Analysis Data Management	
Visibility	

[1] Type 2 for <Number of Steps>. We will apply two steps of displacement on the insert: downward and then upward.

[2] Turn on <Large Deflection>. Leave other settings as their default values. We may come back later on.

13.4-6 Set Up Environment Conditions

[2] Set up a <Frictionless Support> on this edge and the edge in the next step.

[4] Set up a <Displacement> on this edge.

[3] And this edge.

[1] Set up a <Fixed Support> on this edge.


Details of "Frictionless Support"

Scope	
Scoping Method	Geometry Selection
Geometry	2 Edges
Definition	
Type	Frictionless Support
Suppressed	No


Details of "Displacement"

Scope	
Scoping Method	Geometry Selection
Geometry	1 Edge
Definition	
Type	Displacement
Define By	Components
Coordinate System	Global Coordinate System
X Component	Free
Y Component	Tabular Data
Suppressed	No
Tabular Data	
Independent Variable	Time


[5] Select <Tabular Data> for <Y Component>.



13.4- Set Up Result Objects



[3] Select <Displacement>. Workbench will calculate the forces required to displace the insert.



13.4-8 Solve the Model and View the Results


Solution (A6)

- Solution Information
- Total Deformation
- Force Reaction

Details of "Solution Information"

Solution Information	
Solution Output	Force Convergence
Newton-Raphson Residuals	0
Update Interval	2.5 s
Display Points	All

[1] Highlight <Solution Information>, select <Force Convergence>, and click <Solve>.



A: Static Structural (ANSYS)
 Total Deformation
 Type: Total Deformation
 Unit: mm
 Time: 2


0.0038002 Max
 0.003378
 0.0029557
 0.0025335
 0.0021112
 0.001689
 0.0012667
 0.00084449
 0.00042225
 0 Min



ANSYS
 Noncommercial use only

[2] Highlight <Total Deformation>, animate the deformation. The data shows that it takes only one substep for the first step. We need smaller initial time step for smooth animation and curve plotting.

Geometry / Workbench / Print Preview / Report Preview /



Tabular Data

	Time (s)	Minimum (mm)	Maximum (mm)
1	1	0	18.56
2	1.35	0	13.29
3	1.525	0	9.6566
4	1.7	0	6.0879
5	1.875	0	2.5351
6	2	0	3.9002e-003

Details of "Analysis Settings"

Step Controls	
Number Of Steps	2
Current Step Number	1
Step End Time	1 s
Auto Time Stepping	On
Define By	Time
Initial Time Step	0.1 s
Minimum Time Step	1.e-002 s
Maximum Time Step	0.1 s
Solver Controls	
Solver Type	Program Controlled
Weak Springs	Program Controlled
Large Deflection	On
Inertia Relief	Off
Nonlinear Controls	
Output Controls	
Analysis Data Management	
Visibility	

[1] Set up
<Analysis Settings>
for the first step.

Details of "Analysis Settings"

Step Controls	
Number Of Steps	2
Current Step Number	2
Step End Time	2 s
Auto Time Stepping	On
Define By	Time
Carry Over Time Step	On
Minimum Time Step	1.e-002 s
Maximum Time Step	0.1 s
Solver Controls	
Solver Type	Program Controlled
Weak Springs	Program Controlled
Large Deflection	On
Inertia Relief	Off
Nonlinear Controls	
Output Controls	
Analysis Data Management	
Visibility	

[2] Set up
<Analysis Settings>
for the second
step.

[3] Turning on
<Carry Over Time
Step> is to use the
time step value of
the last substep of
the first load step
as the initial time
step value for this
step.


Solve

[4] Solve.

[5] Highlight <Force
Reaction> to view the
required forces.

Graph

Animation



[7] It requires 230 N
to pull out.

[6] It requires 180 N
to snap in.

[8] The curve is
symmetric.
Remember that we
didn't take the
friction into account.

Tabular Data


	Time (s)	Force Reaction (Y) (N)
1	0.1	-15.334
2	0.2	-32.008
3	0.3	-57.293
4	0.4	-94.737
5	0.5	-147.37
6	0.6	-179.94
7	0.7	-79.567
8	0.8	230.12
9	0.9	180.13
10	1	-2.8357e-004
11	1.035	77.555
12	1.07	138.77
13	1.1225	205.43
14	1.2012	227.23
15	1.28	116.12
16	1.38	-113.82
17	1.48	-159.32
18	1.58	-103.61
19	1.68	-63.691
20	1.78	-36.345
21	1.88	-18.196
22	1.94	-11.202
23	2	-1.0771e-009

Details of "Frictional - Prong To Insert"

Scope	
Scoping Method	Geometry Selection
Contact	4 Edges
Target	4 Edges
Contact Bodies	Front
Target Bodies	Insert
Definition	
Type	Frictional
Friction Coefficient	0.2
Scope Mode	Manual
Behavior	Symmetric
Suppressed	No
Advanced	
Formulation	Pure Penalty
Interface Treatment	Add Offset, No Ramping
Offset	0. mm
Normal Stiffness	Program Controlled
Update Stiffness	Never
Pinball Region	Program Controlled
Time Step Controls	None

[9] Highlight
<Frictionless - Prong To Insert>, change the
<Type> to <Frictional>,
and type 0.2 for
<Friction Coefficient>

[10] Solve again. It
fails after a few
iterations, because of
too many bisections.




Details of "Analysis Settings"

Step Controls	
Number Of Steps	2
Current Step Number	1
Step End Time	1. s
Auto Time Stepping	On
Define By	Time
Initial Time Step	2.e-002 s
Minimum Time Step	2.e-003 s
Maximum Time Step	0.1 s
Solver Controls	
Solver Type	Program Controlled
Weak Springs	Program Controlled
Large Deflection	On
Inertia Relief	Off

[11] Reduce
the initial time
step to 0.02 s.

Details of "Analysis Settings"

Step Controls	
Number Of Steps	2
Current Step Number	2
Step End Time	2. s
Auto Time Stepping	On
Define By	Time
Carry Over Time Step	On
Minimum Time Step	2.e-003 s
Maximum Time Step	0.1 s
Solver Controls	
Solver Type	Program Controlled
Weak Springs	Program Controlled
Large Deflection	On
Inertia Relief	Off




[12] Solve again.
It again fails after
a few iterations.

Details of "Frictional - Prong To Insert"

Scope	
Scoping Method	Geometry Selection
Contact	4 Edges
Target	4 Edges
Contact Bodies	
Target Bodies	
Definition	
Type	Frictional
Friction Coefficient	0.2
Scope Mode	Manual
Behavior	Symmetric
Suppressed	No
Advanced	
Formulation	Pure Penalty
Interface Treatment	Add Offset, No Ramping
Offset	0. mm
Normal Stiffness	Program Controlled
Update Stiffness	Each Equilibrium Iteration
Pinball Region	Program Controlled
Time Step Controls	None

[13] Highlight <Frictional - Prong To Insert>, select <Each Equilibrium Iteration> for <Update Stiffness>. This usually helps convergence.

[14] Solve again. It takes a while (about 25 minutes in my computer) to complete the solution.





```

FORCE CONVERGENCE VALUE = 327.2      CRITERION= 0.2962
EQUIL ITER 1 COMPLETED. NEW TRIANG MATRIX. MAX DOF INC= -0.1956
LINE SEARCH PARAMETER = 0.5779      SCALED MAX DOF INC = -0.1131
FORCE CONVERGENCE VALUE = 179.4      CRITERION= 0.2133
EQUIL ITER 2 COMPLETED. NEW TRIANG MATRIX. MAX DOF INC= 0.1267E-01
LINE SEARCH PARAMETER = 1.000        SCALED MAX DOF INC = 0.1267E-01
FORCE CONVERGENCE VALUE = 34.92      CRITERION= 0.2253
EQUIL ITER 3 COMPLETED. NEW TRIANG MATRIX. MAX DOF INC= 0.1004
LINE SEARCH PARAMETER = 0.6958      SCALED MAX DOF INC = 0.6985E-01
FORCE CONVERGENCE VALUE = 30.58      CRITERION= 0.2916
EQUIL ITER 4 COMPLETED. NEW TRIANG MATRIX. MAX DOF INC= 0.1047E-01
LINE SEARCH PARAMETER = 1.000        SCALED MAX DOF INC = 0.1047E-01
FORCE CONVERGENCE VALUE = 5.867      CRITERION= 0.3076
EQUIL ITER 5 COMPLETED. NEW TRIANG MATRIX. MAX DOF INC= 0.1734E-01
LINE SEARCH PARAMETER = 0.8577      SCALED MAX DOF INC = 0.1487E-01
FORCE CONVERGENCE VALUE = 2.724      CRITERION= 0.3313
EQUIL ITER 6 COMPLETED. NEW TRIANG MATRIX. MAX DOF INC= 0.3472E-01
LINE SEARCH PARAMETER = 1.000        SCALED MAX DOF INC = 0.3472E-03
FORCE CONVERGENCE VALUE = 0.2257      CRITERION= 0.3382    <<< CON
>>> SOLUTION CONVERGED AFTER EQUILIBRIUM ITERATION 6
*** LOAD STEP 2 SUBSTEP 114 COMPLETED. CUM ITER = 1889
*** TIME = 1.89395 TIME INC = 0.228325E-01
*** AUTO TIME STEP: NEXT TIME INC = 0.43249E-01 INCREASED (FACTOR = 1.5000)

```

[15] Many of line search take place.



Wrap Up

Save the project and exit Workbench.